



U.S. Department of Transportation

National Highway Traffic Safety Administration

#### Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\* \*\*\* \*\*\*



Case Vehicle (A): 1998 Ford Type: F-150, 4x2 3-door pickup

Driver: 20-year-old male

CDC: 01-RYEW-3, 99-0000-0

Vehicle (B): 1994 Ford Type: Taurus, 4-door sedan Driver: 30-year-old female CDC: 11-FDEW-2, 09-LPEW-2

#### **SITUATION**

(Slide 1) Case vehicle (A) was traveling north in the northbound lane of a straight section of a dry asphalt, two-lane roadway, with a speed limit of 80 kph (50 mph), and was approaching a four-leg intersection. Vehicle (B) was traveling south in the southbound lane of the same roadway. (Slides 2, 3) As case vehicle (A) entered an intersection with a two-lane road, the driver of case vehicle (A) began to make a left turn across the path of vehicle (B) to travel west. The driver of vehicle (B) was unable to stop in time, and the front of vehicle (B) struck the right-front corner of case vehicle (A). The impact caused case vehicle (A) to rotate counterclockwise and side-slap vehicle (B) before it came to rest facing southwest. After the side-slap, vehicle (B) rotated clockwise and came to rest facing northwest.

#### GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 4) Damage to case vehicle (A) was moderate. The direct-damage length was 200 cm. It began at the right-front corner and extended rearward along the right fender to approximately the mid-point of the right-front door. The maximum crush was 50 cm and occurred at the right-front fender corner. The right wheelbase was reduced 8 cm, and the left wheelbase was extended by 8 cm. The side-slap impact produced no residual crush to the right-rear bumper corner.

(Slide 5) Damage to vehicle (B) was severe. The direct-damage length was 150 cm. It began at the right-front bumper corner and involved the entire frontal plane. The maximum crush was 38 cm and occurred 78 cm inboard of the right-front bumper corner. The right wheelbase was reduced 19 cm, and the left wheelbase was extended by 2 cm. The direct damage from the side-slap impact began just forward of the left-rear axle, and the maximum crush occurred just forward of the left C-pillar.

Using the WinSMASH accident-reconstruction program and (slides 6, 7, 8, 9, 10, 11) c-values for case vehicle (A) and vehicle (B), the following impact severities were calculated:

	Calculated V		Velocity Change	- kph (mph)
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	delta V	20 (13)	-16 (-10)	-13 (-8)
Vehicle (B)	delta V	29 (18)	-25 (-16)	15 (9)

#### **DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)**

#### Exterior

(Slides 12, 13, 14, 15, 16) The right side of the front bumper was crushed rearward. The right headlight assembly was broken. The right side of the hood, the right fender, and the right lower-A-pillar were crushed laterally. The right-front wheel strut was torn from the vehicle. The right door was bowed out, and the windshield was damaged by impact forces. Both right doors were jammed shut, but the left door remained closed and operational. The hood latch was not damaged, and was operational. Both hood hinges were slightly deformed, but not separated. The rear edge of the hood was not elevated, and it did not contact the windshield.

#### Interior

(Slides 17, 18, 19, 20, 21) This vehicle was equipped with both steering-wheel and passenger frontal-impact airbags, which deployed during the right-side impact. (Slides 22, 23, 24, 25, 26, 27) There was no damage to the airbag skins or module doors/flaps. (Slide 28) The steering-wheel rim was not deformed, and the steering-wheel column was not rotated. (Slides 29, 30, 31, 32, 33) The windshield was cracked from contact with the rearview mirror, as well as from the deformation of the right cowl area. The following intrusions were noted and measured:

Location	Component	Distance (cm)	Direction
right front	kickpanel	22	to left
right front	door	12	to left
right front	toepan	7	to rear
right front	instrument panel	5	to rear

#### OCCUPANT INJURIES AND KINEMATICS

The 6-ft, 3-in, 175-lb, 20-year-old male driver (slides 34, 35) was wearing the available three-point belt, as indicated by a webbing imprint on the D-ring, and the steering-wheel airbag

deployed. On impact, the driver moved forward and to the right, into the shoulder belt and the airbag. (Slide 36) He sustained a fracture to his right thumb, probably from contact by the steering wheel rim, but possibly from the airbag flinging his hand into the rearview mirror. He also sustained a fracture of the distal 4<sup>th</sup> phalange, probably from the airbag flinging his hand into the rearview mirror. (Slide 37) He sustained an abrasion to the right knee, probably from contact with the knee bolster.

The following table and (slide 38) attached drawing summarize the injuries sustained by the driver.

Occupant: Driver Restraints: 3-point belt worn; airbag deployed

Age: 20 years Stature: 191 cm (6 ft, 3 in)


Gender: Male

Mass: 79 kg (175 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Fracture, distal right thumb	1		Steering-wheel rim	Rearview mirror/airbag fling
Fracture, distal right 4 <sup>th</sup> phalange	1		Rearview mirror	
Abrasion, right knee	1		Knee bolster	
Maximum A.I.S. Level	1			
Injury Severity Score	2			

Duplicate columns 1-8 Module G I Format ( from the previous card. 9 10 1	0 2	GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION		ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE	
HOUR OF COLLISION	_	(0) NO (1) YES (9) UNKNOWN	$\mathcal{Q}_{\overline{33}}$
(24 HOUR CLOCK) 21 24		ROAD ALIGNMENT VERTICAL PLANE	
LOCATION STATE:		<ul> <li>(1) LEVEL</li> <li>(2) CREST OF HILL</li> <li>(3) SLOPE (2%)</li> <li>(4) BOTTOM OF HILL</li> <li>(9) UNKNOWN</li> </ul>	3 34
STATE FIPS CODE	25 26	ROAD ALIGNMENT HORIZONTAL PLANE	
AREA (1) URBAN (2) RURAL (9) UNKNOWN	2,	(1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER:	35
ENVIRONMENTAL CONDITIONS  LIMITED-ACCESS HIGHWAY  (0) NO  (1) YES  (9) UNKNOWN	<u>Ø</u>	SURFACE COVERING  (10) DRY  (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	36 37
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)  (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	2 29	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN  (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR  (8) NOT APPLICABLE	2 30	VISIBILITY LIMITATION (FOR CASE VEHICLE)  (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE	<u>Q</u>
TYPE OF ROAD SURFACE  (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN	31	(4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN  VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)	
ROAD DEFECTS  (0) NO (1) YES (9) UNKNOWN	<u></u>	(0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	39
2			

		GENERAL INFORMATION	GI-3
CRASH DETAILS  CASE VEHICLE AND OBJECT  (0) NO (1) YES (9) UNKNOWN  CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT	<u>Ф</u> 47	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE)  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	<u>3</u>
(2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN  CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT)  (0) NO (1) YES (9) UNKNOWN	<b>D</b>	DRIVER IMPAIRMENT  DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE)  (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>O</u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE  (0) NO (1) YES (9) UNKNOWN	50	DRIVER ALCOHOL BAC (CASE VEHICLE)  (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	. 8 <u>\$</u>
CASE VEHICLE AND CONTACTED STOPPED VEHICLE  (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	<u>D</u>
STOPPED CASE VEHICLE AND CONTACTED VEHICLE  (0) NO (1) YES (9) UNKNOWN  TOTAL NUMBER	52	LIST IMPAIRMENTS MENTIO	NED:
OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH  (8) 8 OR MORE (9) UNKNOWN  ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE)	53	POST - CRASH DETAIL  MANNER CASE VEHICLE LEFT SCENE  (1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE	2
(0) NO (1) YES (9) UNKNOWN	<u>u</u>	(4) TOWED, REASON UNKNOWN (9) UNKNOWN	60



Duplicate columns 1-8 from the previous card.  Module O V Format 0 11	4 OTHER VEHICLE OV-1
MAKE: Ford  MODEL: Taurus 4-do	
VIN LEALPSQU	JORG REPORT
MANUFAC/BODY CODE $\frac{1}{30}$ $212$	VEHICLE TYPE
MAKE/MODEL CODE <u>© 27</u>	PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR
MODEL YEAR $\frac{1}{39} \frac{9}{7} \frac{7}{4}$	(20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT
VEHICLE MASS (kg) $\Phi$ $\Phi$ $\Phi$ $\Phi$	(27) COMPACT (28) INTERMEDIATE (29) FULL
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107°,
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	E.G. PANEL TRUCK, SUBURBAN)  (16) PICKUP TRUCK WITH CANOPY/SHELL COVER  (17) PICKUP CAR WITH CANOPY/SHELL COVER  (21) MOTOR HOME  (22) PICKUP TRUCK WITH SLIDE-IN CAMPER  (23) PICKUP CAR WITH SLIDE-IN CAMPER
TRAVELING SPEED (km/h) 99	(31) CHASSIS-MOUNTED CAMPER
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRUCK  (11) VAN  (12) PICKUP TRUCK  (13) UNKNOWN LIGHT TRUCK  (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)  (16) PICKUP TRUCK WITH CANOPY/SHELL COVER  (22) PICKUP TRUCK WITH SLIDE-IN CAMPER  (30) UNKNOWN TRUCK TYPE  (31) CHASSIS-MOUNTED CAMPER  (33) DELIVERY VAN (WALK-IN)
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE  (0) O - NO INJURY (1) C - POSSIBLE INJURY	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)
(2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE)	BUS  (40) UNKNOWN BUS TYPE  (41) SCHOOL BUS ?  (42) INTERCITY BUS (BETWEEN CITIES)  (43) TRANSIT BUS (INTRACITY)  (44) STREETCAR (ON TRACKS)
(9) UNKNOWN	(68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER) (99) UNKNOWN
	WHEELBASE (cm) (999) UNKNOWN  369 58 59 60

Duplicate columns 1-8 from the previous card.

Module O V Format 0 2 9 10 11 12 OTHER VEHICLE

OV-2

#### **ORIGINAL SPECIFICATIONS**

Wheelbase \_\_

269 cm

Front Overhang

1 0 2 cm

**Curb Weight** 

1408 kg

Rear Overhang

1 6 cm

Average Track Width

$$155 cm$$

Undeformed End Width (UEW)

1 50 cm

Overall Length

Engine Displacement


3.<u>0</u> .


Overall Width (OAW) 19 8 0 cm


Engine: # of Cylinders


<u>6</u>


#### **VEHICLE DAMAGE**











#### FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)



Front-End Overlap (Percent) = DDL


98 %


Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)
OAW

9 4 %

Duplicate columns 1-8 Module V D Format from the previous card.	<u> 4</u> 1 12		VEHICLE DESCRIPTION	VD-1
MAKE: Ford MODEL: F-150			CARGO:	
VIN 2 FIRX O	8 T	. <u>7</u> (	WC M	29
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{2}{1}$	12	STOLE	N VEHICLE	
MAKE/MODEL CODE 310	28/38		ES IOT COLLECTED	8
MODEL YEAR	8 42	(9) UI	INKNOWN	
VEHICLE MASS (kg) $\bigcirc$	48		STRUCTURE ODY & FRAME	]
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC)  49	54	(3) IN (4) BC	NITIZED VTEGRAL-STUB FRAME ODY & PLATFORM FRAME E.G. <i>VW BUG)</i>	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	9	(5) PA (7) OT	ARTIALLY UNITIZED THER: NKNOWN	
TRAVELING SPEED (km/h)  (000) PARKED OR STOPPED (995) JUST STARTING UP	59	TRANSM	MISSION	
(996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN		(2) MA	ONE UTOMATIC ANUAL NKNOWN	64
VEHICLE TYPE		LOCATIO	ON OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR)	<u>3</u> <u>60</u> 61	SELECT	FOR LEVER	3
(13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE		(3) CC (7) OT	OLUMN	65
(18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN  MULTIPURPOSE PASSENGER VEHICLE		CTEED!A	NO.	
(21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN		(1) PO (2) MA	DWER ANUAL	
(24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME		(9) UN	IKNOWN	
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED)		BRAKES (1) PO		
(33) PICKUP TRUCK, LARGE (99) UNKNOWN		(2) MA		67

		VEHICLE DESCRIPTION V	'D-2
TYPE OF BRAKES  (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	2	WHEELBASE <i>(cm)</i> (999) Unknown	<u>353</u>
BRAKE ANTI-LOCK DEVICE  (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN	1 69	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED  (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER	<u>P</u>
AIR CONDITIONING IN VEHICLE  (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 70	(9) UNKNOWN	
TYPE OF DRIVE  (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN	71	FIELD INVESTIGATOR INSTRUCTIONS:  1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND <u>SHADING THE DAMAGED AREAS</u> ON THE LARGE SKETCH ON PAGE VD-3.	
DUAL REAR WHEELS  (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE.	·
ORIGINAL TYPE OF RESTRAINT SYSTEM  (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>3</u>	3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR.  4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  EXAMPLES:	
EQUIPPED WITH ROLL BAR  (0) NO (1) YES (9) UNKNOWN	<b>₫</b>	FRONT OR REAR	
TYPE OF ROOF  (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	75	ROOF (REFERENCE TO TOP OF DOOR SILL)	





# FRONTAL CRASH OVERLAP Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Front-End Overlap (Percent) = DDL UEW Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW) OAW Direct Damage Length (DDL) 35 37 Cn 37 Cn 38 39 Cn 37 Cn 38 39 M Au 40 41

DAMAGE DA-1 Duplicate columns 1-8 Module D A Format 0 2 from the previous card. 10 CASE VEHICLE PRIMARY CDC CONTACTED VEHICLE ASSOCIATED CDC PRIMARY **EVENT NUMBER** IMPACT SPEED (km/h) **ESTIMATED BY** CRUSH (cm) **CDC #1 CDC #2** Duplicate columns 1-8 Module D A Format 0 3 from the previous card. 10 CASE VEHICLE SECONDARY CDC CONTACTED VEHICLE ASSOCIATED CDC SECONDARY **EVENT NUMBER** IMPACT SPEED (km/h) **ESTIMATED BY** CRUSH (cm) **CDC #1 CDC #2** CODES **EVENT NUMBER IMPACT SPEED ESTIMATOR CRUSH** (8) NOT APPLICABLE (1) INVESTIGATOR (998) NOT APPLICABLE (9) UNKNOWN (2) DRIVER (NO VEHICLE/DAMAGE) (3) POLICE (999) UNKNOWN **IMPACT SPEED** (4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM CDC (998) NOT APPLICABLE SPECIFY: (999) UNKNOWN (7) OTHER: (9800000) NOT APPLICABLE (8) NOT APPLICABLE (9900000) UNKNOWN (NO VEHICLE/NO IMPACT)

Duplicate columns 1-8 from the previous card.

Module D A Format 0 1 1 1 12

MAXIMUM SHEET METAL CRUSH

(cm) (999) UNKNOWN

FRONT 
$$Oldsymbol{Q} Oldsymbol{5} Oldsymbol{0} Oldsymbol{1} Oldsymbol{$$

## CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE

NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER?

(0) NO (1) YES

	·	<b>-</b>	
EVENT NUMBER	IMPACT LOCATION  (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN	IMPACT CONFIGURATION FOR CODES, SEE TABLE ON PAGE DA-3.	OBJECT/VEHICLE CONTACTED FOR CODES, SEE TABLE ON PAGE DA-4.
# 1	1	. 41	<u>28</u>
#2	32 1	$\frac{4}{3}$	$\frac{28}{41}$
#3	42	<del>- 44</del>	46
#4	47	<del></del> <del></del>	<del></del> <del></del>
#5	52		56
#6	57	59	61
#7	62	<del></del>	66

#### **CODES FOR** IMPACT CONFIGURATION

#### **FRONT OF CASE VEHICLE**

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **LEFT SIDE OF CASE VEHICLE**

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **REAR OF CASE VEHICLE**

- (31) AND <u>FRONT</u> OF CONTACTED VEHICLE (33) AND <u>SIDE</u> OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **RIGHT SIDE OF CASE VEHICLE**

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **OTHER**

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

#### **ROLLOVER**

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

#### UNKNOWN

(99) IMPACT TYPE UNKNOWN

#### CODES FOR VEHICLE/OBJECT CONTACTED

#### VEHICLE/OBJECT GROUPS

- NO OBJECT
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- (98)OTHER (DESCRIBE)
- UNKNOWN (99)

#### PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

#### SIZE

#### WHEELBASE

SUB-MINI < 2286 mm ( < 90") MINI 2286 - 2412 mm (90" - 94.9") SUB-COMPACT 2413 - 2539 mm (95" - 99.9") COMPACT 2540 - 2666 mm (100° - 104,9°) INTERMEDIATE 2667 - 2793 mm (105" - 109.9") **FULL** 2794 - 2920 mm (110" - 114.9") LARGE 2921 - 3174 mm (115" - 124.9") LIMOUSINE > 3175 mm ( > 125")

#### MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107°. E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

#### **TRUCK**

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN)
- (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

#### BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

#### **MOTORCYCLE**

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc
- (52) 76 125 cc
- (53) 126 250 cc
- (54) 251 500 cc
- (55) 501 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

#### SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

#### **OBJECT**

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION
- (91) GUARD RAIL, MIDDLE OR UNKNOWN
- (92) GUARD RAIL, TRAILING SECTION
- (93) GUARD POST (TIMBER, METAL, CONCRETE) (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

Duplicate columns 1-8 Module C F from the previous card. 9 10	R Format 0 1 12		H RECONSTRUC r av	TION CR-1
		PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13	-	<u>a</u>	
ΔV (km/h) TOTAL	$ \underline{\mathcal{O}}_{14} \underline{\mathcal{J}}_{15} \underline{\mathcal{O}} $	2 3 3	9 9 9 50	$\frac{9}{66} \frac{9}{67} \frac{9}{68}$
- LONGITUDINAL*	$\frac{-\cancel{0}\cancel{1}\cancel{6}}{\cancel{1}\cancel{2}}$	$\sum_{35} \underline{0} \underline{\lambda} \underline{5}$	$\frac{9}{51} \frac{9}{9} \frac{9}{54}$	$\frac{99}{69} \frac{9}{72}$
LATERAL*  *NOTE: THESE ΔV COMPONENTS  MUST INCLUDE SIGN.  EXAMPLES: 10 km/h = ± 0 1 0	$\frac{-013}{21}$	$+\frac{015}{39}$	9955	9999
-7 km/h = : 007  ENERGY DISSIPATED BY CRUSH (kj)	<u>003</u> 25 31266	<u>0075</u>	9999	999
RECONSTRUCTION	51200	74735		
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	$\frac{2}{2}$		$\mathcal{Q}_{\frac{2}{63}}$	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL			<b></b> 0.1	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE	_			
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<b>2</b> 31		5 65	
COMPUTER PROGRAM SPECIFY: WINS MASH				

	R Format 0 2		H RECONSTRUCTES	TION CR-2
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		2/47	
EBS (km/h) TOTAL	<u>2</u> 23	$\frac{\mathcal{O}_{32}}{32} \frac{1}{34}$	$\frac{9}{48} \frac{9}{49} \frac{9}{50}$	999
LONGITUDINAL*	= 0L 8 20	$\frac{-}{35}$ $\mathcal{Q}$ $\frac{7}{38}$	9999	9999
LATERAL* *NOTE: THESE EBS COMPONENTS	<u>-015</u>	$\frac{1}{39} \oplus \frac{16}{42}$	$\frac{9}{55} \frac{9}{7} \frac{9}{7} \frac{9}{58}$	$\frac{9}{73} \frac{9}{76} \frac{9}{76}$
MUST INCLUDE SIGN.  EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = ± <u>0</u> <u>0</u> <u>7</u>				
ENERGY DISSIPATED BY CRUSH (ki)	<u>ØØ 6 1</u> 25 615 74 28	<u>Ø</u> <u>Ø</u> 75	9999	$\frac{9}{77} = \frac{9}{9} = \frac{9}{80}$
RECONSTRUCTION	0/3:72	74732		
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22		<u> </u>	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT	. J			
(10) OTHER:			:	
MODE				

 CDC ONLY
 CDC & DETAILED DAMAGE
 TRAJECTORY & CDC
 TRAJECTORY & CDC & DETAILED DAMAGE
 NOT RECONSTRUCTED

COMPUTER PROGRAM SPECIFY: WINSMASH

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u>

CRASH RECONSTRUCTION

O FREW ?

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C  $_{\rm 1}$  TO C  $_{\rm 6}$  FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

CASE VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	
	Begins (P) Front bumper corner		
	G C C		
	C6 C5 C5		
	C4	DL	
PLANE:		UDL	

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other \_\_\_\_
- (9) Unknown



C1

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line. Specific Plane **Direct Damage** Impact of Impact Length Max Field  $C_3$  $C_1$  $C_2$  $C_4$  $C_5$ ±D  $C_6$ Number C-Measur. (DDL) Crush Above sill 50 260 180 0 015 016 029 1 00 15 16 17 13 18 19 20 2

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u> 12

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C  $_{\rm 1}$  TO C  $_{\rm 6}$  FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

OTHER VEHICLE


**LOCATOR** 

3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.

4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
	Begns Ofront bumper Corner	B.C. to B.C.



DL 150

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other
- (9) Unknown

**CRUSH PROFILE IN CENTIMETERS** 

	NOTE: Each	line in the ta	ble below is a	separate rec	cord (card).			umns 1 - 1	2 for each	n complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direc Length (DDL)	t Damage Max Crush	   Field   L	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
	Bumper	150	C4	130	19	23	30	39	43	52	Ø
					-16	-6	-1	-1	-6	-16	
					3	17	29	38	37	36	
· -											
1	1	150	038	130	003	017	027	038	037	036	+000
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32		36 37 38	39 40 41	42 43 44 45
		·									
2											

Duplicate columns 1-8 from the previous card.  Module W 7 9 10			WHEELS AND TIRES WT-1
WHEELSDAMAGED  (0) NO (1) YES (9) UNKNOWN	LF RF RR LR	13   O   O   16	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S)  LF LT265 70 R17  RF LT265 70 R17  RR LT265 70 R17
TIRE TREAD TYPE  (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	4 4 4 20	LR <u>LT26570R17</u>
CARCASS CONSTRUCTION  (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3213 3 3 3 24	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:			

Duplicate columns 1-8 Module F T Format 0 from the previous card. 9 10 11		FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL  (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE  (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	8 21
MAIN TANK LOCATION	322	AUXILIARY TANK LOCATION	888
MAIN FILLER CAP LOCATION	113	AUXILIARY FILLER CAP LOCATION	88 25 27
MAIN TANK MATERIAL	20	AUXILIARY TANK MATERIAL	<u>₹</u> 28

#### TANK AND FILLER CAP LOCATION CODES

#### FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

#### SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

#### THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

#### **TANK MATERIAL CODES**

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

Duplicate columns 1-	8
from the previous car	d.

Module <u>F</u> <u>L</u> Format <u>0</u> <u>1</u> 12

#### FUEL LEAKAGE

FI -1

#### DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.



	1	11	Ш	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
- #1	14 15		_	<u></u>	<del></del>	21
#2	22 23					29
#3	30 31				<del></del>	37
#4	38 39			<del></del>		45
#5	46 47					53

#### LEAKING COMPONENT

#### TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

#### **DELIVERY SYSTEM**

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

#### **EVAPORATIVE EMISSION CONTROL SYSTEM**

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

#### **EEC SYSTEM (CONTINUED)**

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT. COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

#### II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

#### III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

#### IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

#### V LOCATION OF LEAK

#### FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P. BETWEEN COWL & **REAR BULKHEAD**
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

#### SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 from the previous card. 9 10 1		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAG (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE  (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE  (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE?  (0) NO (1) YES	17

PROVIDE NOTES IF FIRE OCCURRED.


(0) NO (1) YES (9) UNKNOWN

Duplicate columns 1-8 Module E D Format from the previous card.	0 1 EXTERIOR DAMAGE	ED-1
HOOD PERFORMANCE  FOR THE FOLLOWING, USE CODES:  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	STEERING COL FLEXIBLE COUPLING  FLEXIBLE COUPLING TYPE  (0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE	9 26
HOOD LATCH(ES)RELEASED	(CIRCLE EACH) (7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED  COUPLING- (USE CODES	
-DAMAGED	14 COUPLINGDAMAGED	<u>9</u>
-JAMMED	(USE CODES 15 FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	9 28
HOOD HINGESLEFT, DAMAGED	<u> </u>	
-LEFT, SEPARATED (COMPLETE)		· 
-RIGHT, DAMAGED	L ENG COMPART TELESCOPING UNIT	
-RIGHT, SEPARATED (COMPLETE) HOOD REMAINED ON VEHICLE	TYPE OF UNIT	8 8 30
REAR EDGE OF HOODELEVATED	ORIGINAL LENGTH (mm)	
-CONTACTED WINDSHIELD	F (OR H):	
-PENETRATED WINDSHIELD	F (OR H):  TELESCOPED LENGTH (mm)  G:	
HOOD LATCH LOCATION		
(1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN	DIFFERENCE (mm)  F (OR H) - G  (IF LESS THAN 15mm, ENTER *000*.)	
Engine or Transmission Mount separation <i>(complete)</i> (0) NO (1) YES (9) UNKNOWN	(22)	8 8 8 33

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<b>Q</b> <sub>34</sub>	LEFT DOORS  HOW DID DOORS OPEN DURING COLLISION?  USE CODES:	
LEFT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(0) DOOR DID NOT OPEN  OPENED BECAUSE OF  (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER LOWER	<b>Q</b> 35 <b>Q</b> 36	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	<b>9</b> 3
-B-PILLAR, UPPER	<b>Q</b> 37 <b>Q</b> 38	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES	
-C-PILLAR, UPPER	<b>7</b>	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	₩ 45 8 46
-D-PILLAR, UPPER	8 41 8 42		46


	1	EXTERIOR DAMAGE	ED-3
		OTHER REAR DAMAGE	
REAR DOOR  REAR DOOR TYPE  (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING	<b>Q</b>	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>4</u>
TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN		SPARE TIRE  (0) NO SPARE TIRE	8
Hatchback One-way		(1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED (9) UNKNOWN	51
Two-way or		TRAILER HITCH TYPE	
Clamshell		(0) NO HITCH  BALL-AND-SOCKET TYPES  (1) TEMPORARY FRAMEWORK (E.G.	52
Single door		RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING	
Double door		OTHER TYPES	
HOW DID DOOR OPEN DURING COLLISION?		(5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN)	
(0) DOOR DID NOT OPEN OPENED BECAUSE OF	<b>4</b> 8	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED	
(1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN		TRAILER TYPE (AT TIME OF COLLISION)  (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	<u>\$</u>
DOOR JAMMED CLOSED  (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	49	(-)	

		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<b>D</b> 54	RIGHT DOORS  HOW DID DOORS OPEN DURING COLLISION?  USE CODES:  (00) DOOR DID NOT OPEN	
RIGHT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		OPENED BECAUSE OF  (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER LOWER	9 55 4 56 56 56 56 56 56 56 56 56 56 56 56 56	(98) NOT APPLICABLE <i>(NO DOOR)</i> (99) UNKNOWN -FRONT -REAR	
-B-PILLAR, UPPER  LOWER  -C-PILLAR, UPPER	Ø 57 Ø 58	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
LOWER -D-PILLAR, UPPER	59 <b>2</b> 60 <b>3</b> 61	-FRONT	67
LOWER	<b>₹</b>	VAN REAR DOOR TYPE  (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT & LEFT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	69



Duplicate columns 1-8 from the previous card.  Module S C Format 0  11	1 12	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL RIM DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	<b>₽</b>	STEERING WHEEL POSITION AT TIME OF COLLISION  IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED?  EXAMPLES  O'CLOCK = 1, 2, O'CLOCK = 9, 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	3	(NORMAL STRAIGHT AHEAD) O'CLOCK =	
STEERING WHL SPOKE DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE  (1) EXAMPLES:  BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES:  OMNI, 78 -  HORIZON, 78 -	
TILT FEATURE  (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	<b>3</b>	TYPE OF DEVICE  (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED  ORIGINAL DIMENSION (mm)	8 19
SWING-AWAY FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	<b>Q</b> /	A:  DAMAGE DIMENSION (mm)  B:  DIFFERENCE (mm)	
TELESCOPING FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	<u>(18</u>	A - B  (888) NOT COLLECTED  (991) NOT MEASURED/NO APPARENT COMPRESSION  (992) COMPRESSED, AMOUNT UNKNOWN  (993) DEVICE EXTENDED  (997) UNABLE TO MEASURE  (998) NOT APPLICABLE (NOT EQUIPPED)  (999) UNKNOWN	8 8 20

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN		T	<del></del>
ENERGY ABSORBING DEVICE		STEERING WHEEL (CONTINUED)	
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG	<b>Q</b>
ORIGINAL LENGTH (mm)		(3) OTHER (9) UNKNOWN	
C:			
COMPRESSED LENGTH (mm) D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE)			
COMPRESSION (OR EXTRUSION) (mm)			
C - D (OR E) (TOLERANCE: ±10)		·	
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 27		
* (ADD A & B FOR TOTAL COMPRESSION)			
SHEAR CAPSULE SEPARATION (mm)			
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
LT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION			
(0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u>Ø</u>		
COLUMN LATERAL ROTATION			
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<b>₫</b>		




#### 1 = Definitely 2 = Probably 3 = Possible

	1	Intrusi					ION IT-1
		(All Measurements Are in Centimeters)					Dominant
Location of Intrusion	Intruded Component	Comparison Value	_	Intruded Value	=	Intrusion	Crush Direction
13	Kickpanel	78	_	56	=	22	to left
13	Door	76		64	=	12	to left
13	Toepan	70		63	=.	7	rearward
13	Instrument Panel	93	_	85	=	5	rearward
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
					=		

### OCCUPANT CONTACT WORKSHEET

	Interior	Occupant	Body		Confidence Level of
	Component	No. if	Region		Contact
Contact	Contacted	Known	if Known	Supporting Physical Evidence	Point
А	Rearview mirror	1	Hand	Broken off mount	1
В					
С					
D					
E					
F					
G					
Н					
1					



# CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

#### FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

#### SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1)	LEFT	(3) RIGHT		INDIVIDUAL SEAT
(1)	LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1)	LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT	BENCH: FULL WIDTH 4 PASSENGER
(1)	LEFT	(2) CENTER	(5) RIGHT &	BENCH: PARTIAL WIDTH, LEFT
(0)	LEFT & SPACE	(2) CENTER	(5) RIGHT &	BENCH: PARTIAL WIDTH, CENTERED
(4)	ENTIRE \	EHICLE WIDTH		CARGO AREA

#### **EXAMPLES**

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

#### PASSENGER CAR 5 PASSENGERS

#### VAN 12 PASSENGER CAPACITY



# CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

# CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

## CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

#### INDIVIDUAL COMPONENT

#### **INTERNAL**

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

### **EXTERNAL**

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE
- (46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

## GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF <u>ALL</u> THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER A-PILLAR

ROOF SIDE RAIL

- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR WINDSHIELD HEADER
- (53)DOOR PANEL B-PILLAR ROOF RAIL
- (54)DOOR PANEL A-PILLAR ROOF RAIL
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- (56)ROOF RAIL A-PILLAR B-PILLAR WINDOW FRAME
- (57)ROOF RAIL
  A-PILLAR
  B-PILLAR
  C-PILLAR
  DOOR PANEL
- (58)ROOF ROOF RAIL WINDOW FRAME DOOR PANEL
- (59)BACKLIGHT HEADER ROOF C-PILLAR THIRD SEAT-BACK

- (60)ROOF
  ROOF RAIL
  A-PILLAR
  B-PILLAR
  C-PILLAR
  WINDOW FRAME
  DOOR PANEL
  FLOOR PAN
- (61)INSTRUMENT PANEL
  TOE PAN
  WINDSHIELD HEADER
  A-PILLAR
  ROOF RAIL
  WINDOW FRAME
  DOOR PANEL
  ROOF
- (62)ROOF
  ROOF RAIL
  C-PILLAR
  WINDOW FRAME
  FLOOR PAN
  SECOND SEAT
  DOOR PANEL
- (63)ROOF RAIL
  ROOF
  B-PILLAR
  WINDOW FRAME
  FLOOR PAN
  DOOR PANEL
  SECOND SEAT
  FRONT SEAT
- (64)ROOF RAIL
  ROOF OR CONVERTIBLE TOP
  A-PILLAR
  B-PILLAR
  WINDOW FRAME
  WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER ROOF SIDE RAIL
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	<u>I</u> <u>T</u> Format <u>0</u>	1 12			Inti	RUSION	IT-5
WAS THERE OCCUPANT COM  (0) NO <u>DO NOT</u> ANSWER NEX  (1) YES <u>ANSWER</u> NEXT QUEST  (9) UNKNOWN <u>SKIP PAGE</u> .	T QUESTION. <u>SKIP PA</u>	-	13		ON CATAS COMPLETE PA SKIP PAGE.		14
Duplicate columns 1-8 Module from the previous card.  NOTE: Each line in the table below	9 10 11	12	plicate column	s 1 - 12 for eac	h completed li	ine.	
	TRUSIONS IN THIS ( FOR B, F, G, H, I, C FOR C ON PAGE IT-	J ON PAGE	FT TO RIGHT IT-3		ONT TO BAC		S.
A B C INTRUDING INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT		F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21	22-23	24-25	26-27	28-29	30-31	32-33
<u>o 1 13 29</u>	T 00	<u>a</u> a	$\mathcal{Q}\mathcal{Q}$	ØØ	OO	ØΦ	$\Phi\Phi$
<u>02 13 99</u>	1 00	12	QQ	QQ	$\underline{\mathcal{O}}\underline{\mathcal{O}}$	$\underline{\boldsymbol{\sigma}}\underline{\boldsymbol{\sigma}}$	$\Phi \overline{\Phi}$
<u>03 13 03</u>	1 07	$\Phi \Phi$	$\underline{\sigma}\underline{\sigma}$	Q Q	$\overline{Q}$	$\Phi\Phi$	<u>Ø</u> <u>o</u>
<u> </u>	1 05	$\overline{\mathbf{o}}$	$\overline{Q}$	<u>Ø</u> <u>©</u>	$\underline{\mathscr{O}}  \underline{\mathscr{O}}$	<u>Ø</u> <u>Ø</u>	00
0 5							
06							
0 7  NOTE: USE ADDITIONAL PAGE IF MORE THA	AN 7 INTRUSIONS.					.———	
Duplicate columns 1-8 Module 1 from the previous card.	T Format 0	<u>3</u> 12					
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM	IF DA DOOF INTRUS NUMBE	RINTRUSI SION (	DOOR CO ION, CODE DAMAGED MPONENT 1	MPONENT COMPONE DAMAI COMPON	INT GED IENT 2	O IN INCRE  CODES FOR COMPONE	
NUMBER   CAUSE   CODES   FOR CAUSE:	A	- • -	<u> </u>	25 29 33 37	- () () - () () - ()	O) NONE 1) A-PILLAR 2) B-PILLAR 3) C-PILLAR 4) LATCH/STRII 5) HINGES 7) OTHER: 3) NOT APPLIC	(ER

Duplicate columns 1-8 from the previous card.

Module 1 T Format 0 2 11 12

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.

-- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

A INTRUSION - NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT			F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
0 9		<del></del>	_							
1 0										
1 1						<del></del>			<del></del>	
1 2								<del></del>		
1 3								<del></del>		
1 4			_							
<u>1</u> <u>5</u>										
<u>1</u> <u>6</u>										
1 7			_							
1 8			_							
1 9										
2 0										
2 1										
22										
2 3										
2 4										
<u>2</u> <u>5</u>			_							
							<del></del>			

from the previous card.	DES:	) NO		(4) VEC and (	OCCUPANT CONTACT	
	(1	I) YES	d OCCUPANT CONTACT	(8) NOT APPL (9) UNKNOWN		
SIDES	LEFT	RIGHT	FRONT		INSTRUMENT PANEL	1
FRONT DOOR	<b>D</b>	<u> </u>	FOOT CONTROLS	45	UPPER PANEL	
FRONT HARDWARE	<b>D</b>	٥	IGNITION KEYS		MID PANEL	5
FRONT ARMREST	Ö	18	REAR VIEW MIRROR		LOWER PANEL	5
FRONT GLASS	9 19	<u>20</u>	SUNVISOR/FITTINGS (5) LEFT SIDE ONLY	48	ASHTRAY	5
REAR DOOR AREA	<b>Q</b> 21 <b>Q</b>	22	(6) RIGHT SIDE ONLY (7) BOTH SIDES		CONTROL KNOBS & LEVERS	5
REAR HARDWARE REAR ARMREST	<u>0</u>	<b>Q</b> 4 <b>Q</b>	WINDSHIELD TOP MOLDINGS	<b>2</b>	GLOVE COMPARTMENT AREA	6
REAR GLASS	<b>D</b>	<b>©</b>	LEFT A-PILLAR (UPPER OR LOWER)	Φ	INSTRUMENTS	6
ROOF SIDE RAIL	ф Ф Ф	<b>©</b>	RIGHT A-PILLAR (UPPER OR LOWER)	50	PARKING BRAKE RELEASE	
3-PILLAR		ص ش	CENTER CONSOLE	51	PARKING BRAKE PEDAL	
C-PILLAR	<u>31</u> <u>33</u>	<b>Q</b>	TRANSMISSION	52	A/C OR UPPER VENT OUTLETS	
D-PILLAR	<b>3 3 3 5</b>	\$ 36	SELECTOR LEVER	53	HEATER OR A/C DUCTS	6
HEADLINING			RIM, HORN, SPOKE	54	RADIO	
ROOF STRUCTURE	\$\\ \P\ \\ \P\ \\ \P\ \\ \P\ \\ \P\ \\ \P\ \\ \	0 30 4 8 2 8 4 8 4 8 4 8 4 8 4 8 4 8 4 8 4 8			OTHER: *	67
ROOF/SUN ROOF	8	8/42				
OTHER: *	$\frac{8}{43}$	8/4			Rear	
					WINDOW	
					WINDOW HEADER	69
					Consoles	
					VERTICAL	70
					ROOF	8

<sup>\*</sup> MORE THAN ONE ITEM MAY BE NOTED.


Duplicate columns 1-8 Module S T from the previous card.		) <u>2</u> 1 12	SEATS	,	ST-1
FRONT SEAT	DRIVER	PASSEN'F			
TYPE OF FRONT SEAT  (00) NO SEAT  (01) STANDARD BENCH  (02) SPLIT BACK, 50-50  (03) SPLIT BACK, DRIVER WIDE  (04) SPLIT BACK, PASS. WIDE  (05) BUCKET  (06) CAPTAIN'S CHAIR  (07) INDIV. BENCH, 50-50  (08) INDIV. BENCH, DRIVER WIDE  (09) INDIV. BENCH, PASS. WIDE	<u>6</u> 5	<u>Ø</u> 5	FRONT SEAT-BACK  SEAT-BACK TYPE  (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER:  (8) NOT APPLICABLE (9) UNKNOWN	DRIVER  1 30	PASSEN'R
(97) OTHER:	17	18	SEAT-BACK LOCK TYPE  (0) NONE  (1) MANUAL  (2) INERTIA  (3) POWER  (7) OTHER:  (8) NOT APPLICABLE  (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	19	<u></u>	LOCKS HELD  (0) NO  (1) YES  (8) NOT APPLICABLE	34	35
ORIGINAL EQUIPMENT SEATS  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  CONTACT OF SEAT BY REAR OCCUPANT	<u>21</u>	22	(9) UNKNOWN  RECLINER MECHANISM  HELD  (0) NO  (1) YES  (8) NOT APPLICABLE	36	37
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	23	<u>8</u>	(9) UNKNOWN		
FRONT SEAT DAMAGE  (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	<u></u>	HEAD RESTRAINT  HEAD RESTRAINT TYPE  (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	<u>چ</u>	<b>ર</b> ુ
CENTER ARMREST DAMAGED  (0) NO  (1) YES  (7) EQUIPPED, DAMAGE UNKNOWN  (8) NOT APPLICABLE  (NO CENTER ARMREST)  (9) UNKNOWN IF EQUIPPED	$Q_{\overline{27}}$	9	(9) UNKNOWN  REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8	8
FRONT SEAT ROTATION  (0) NONE APPARENT	Q	<b>o</b>	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	8 42	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
(1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE  (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u>	45

			Sı	EATS	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE  (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN  ADJUSTMENT PROVIDED  (1) 2-WAY	DRIVER 2 46	PASSEN'R	SECOND SEAT (CONT.)  CENTER ARMREST DAMAGED  (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	(	<u>2</u>
(2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER:	48	<del>4</del> 9	SECOND SEAT-BACK  LOCKS  FOR THE FOLLOWING, USE:  (0) NO (1) YES (8) NOT APPLICABLE	LEFT	Rіднт
(8) NOT APPLICABLE (9) UNKNOWN  SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN  PRE-CRASH POSITION (1) FORWARD (2) MIDDLE	8 52 <b>2</b> 54	<u>Ø</u> 53  2 55	(9) UNKNOWN LEFT OR CENTER, EQUIPPED  LEFT OR CENTER, HELD  (3) SEAT FOLDED DOWN  RIGHT, EQUIPPED  RIGHT, HELD  (3) SEAT FOLDED DOWN	61 63 63 67	\$\frac{1}{8}\$
(3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN  SECOND SEAT  TYPE OF SECOND SEAT  (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR	LEFT 2	Rіgнт <b>Q</b>	THIRD SEAT  EQUIPPED  BACKREST DAMAGED  CUSHION DAMAGED	<b>Q</b> 8 71 8 73	\$\frac{\phi}{\phi}\rightarrow{\phi}{\phi}\rightarrow{\phi}{\phi}\rightarrow{\phi}{\phi}
(4) JUMP SEAT (5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN  SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<b>Ø</b> 58	<b>Q</b> 59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS  (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN  Applies to any rear-seat position	7	<b>⊅</b> 5


Duplicate columns 1-8 from the previous card.  Module A B Format C 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 12	AIRBAG	, LD
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	PASSENGER SIDE  LOCATION OF AIRBAG  INSTRUMENT PANEL (GLOVE BOX)  EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	16
DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	17
CONDITION OF AIRBAG STEERING WHEEL  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	15	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX)  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	18
DRIVER SIDE  AIRBAG  STEERING WHEEL  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE  AIRBAG INSTRUMENT PANEL (GLOVE BOX)  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT  (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>O</u> 20	MARKED BY CONTACT  (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>C</u>

## AIRBAG AB-2

# AIRBAG NUMBER ON DRIVER SIDE:



# AIRBAG NUMBER ON PASSENGER SIDE:



### NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.

Duplicate columns 1-8 Module O C Format C from the previous card.	) <u>2</u> 1 12	OCCUPANT INFORMATION	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER  ROLE OF OCCUPANT AT 1ST IMPACT  (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14	PHYSICAL DESCRIPTION  AGE IN YEARS  (00) LESS THAN 1 YEAR  (98) 98 YEARS OR OLDER  (99) UNKNOWN  AGE IN MONTHS  (00) LESS THAN 1 MONTH  (25) 25 MONTHS OR OLDER  (99) UNKNOWN	20 20 21 25 22 23
OCCUPANT POSITION  ROW LOCATION  (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN  HEIGHT (cm) (999) UNKNOWN  SEX (1) MALE (2) FEMALE (9) UNKNOWN	$ \frac{079}{24} $ $ \frac{191}{27} $ $ \frac{1}{29} $ $ \frac{1}{30} $
LATERAL LOCATION  (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN  POSTURE  (10) SITTING ON SEAT	1 17	TREATMENT/MORTALITY  (00) NONE  (01) FIRST AID AT SCENE  (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED  (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS  (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT  (05) FATAL, DEAD AT SCENE  (06) FATAL, DEAD WITHIN 24 HOURS (07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER  (09) FATAL, DEAD 31 DAYS TO	<u>Q</u> 2
(11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER:	18 19	1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN  INJURY SEVERITY SCORE (ISS) (99) UNKNOWN  NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH)	Ø 2/34 Ø/35

		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.)  POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	2/36	CHILD SEAT TYPE  (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN  CHILD SEAT MAKE/MODEL	\$ \$ 41 42
RESTRAINT SYSTEM  (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN  ACTIVE RESTRAINT SYSTEM USAGE  (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM  (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO	2 <sub>37</sub>	EJECTION  (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED  AREA OF EJECTION  (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, RIGHT SIDE (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	9 3 4 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
WITH KNEE BOLSTERS  (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS  (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT  (7) OTHER: (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM USAGE  (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	2 40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION  (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	46

# OCCUPANT INFORMATION OC-3 SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (3) BOTH GLASSES AND CONTACTS

(5) LAY CORONER/EXTERNAL EXAM
(7) COMBINATION OF ABOVE (CIRCLE)
(8) NOT APPLICABLE
(9) UNKNOWN

(4) OTHER

**OCCUPANT EYEWEAR** 

(8) NOT APPLICABLE


(0) NONE

(4) OTHER

(1) GLASSES (2) CONTACTS

(9) UNKNOWN

## INDICATE LOCATION OF INJURIES.



Duplicate columns 1-8 from the previous card.

Injury Classification IC-1

NOTE: Each line in the table below is a separate record (card).


Duplicate columns 1 - 12 for each completed line.

## OCCUPANT INJURY CLASSIFICATION

						PRIM	MARY (	OIC.		А	SSOC	IATE	O OIC		COMMENTS
OCCUPANT NUMBER	INJURY NUMBER	PROBAL START I IN 1ST C	BILITY (HOP WITH MOST CONTACT A	IN ORDER OF RIZONTALLY) . F PROBABLE REA COLUMN. BLE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
<u> </u>	<u> </u>	65	06	* Pling	$\omega$	R	E	5	1	_		_			
	$\overline{\omega}\overline{g}$	06			$ \omega $	R	P	<u>5</u>	1	_				_	
	@3	48			K	R	A	I	1			_	_		
	——				_			<u>.</u>	_		_			_	
							-						_		
					_	_	_	_	-		_		_	-	
					_						_	_			
Eine Fine					_	_		_				<del></del>	_	-	
"Occupant Number" for each line						_	_		-						
Number						_	_		-	_			******	-	
ccupant					_		_		-					-	
Duplicate "O					_			_	-			_	_	-	
Pd					_	_		_	-	_					
									-					-	
								_	-			_	_	-	
					_								_	-	
								_		_					
1														_	

## CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

		DOIDLE GOCOL AI	VI CONTACT
FRONT	OF PASSENGER COMPARTMENT	Sides	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
	WINDSHIELD	(19)	
` '		- : :	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(13)	
(54)		(24)	COAT HOOK
(55)	` ,	/==1	
	` ,	(22)	· · ·
(56)	• • •	(21)	WINDOW FRAMES (SIDE)
(81)	,		
(02)		(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(14)	A-PILLAR
		(15)	B-PILLAR
(57)	BENEATH INSTRUMENT PANEL		C-PILLAR
(53)	PARCEL TRAY	• •	D-PILLAR
(48)	KNEE RESTRAINT	()	
(86)	VERTICAL CONSOLE	FLOOR	
, ,		(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	• •	
(20)	. GO. GOTT TOLO (INGL.) ANIMANO DI PARE I EDAL)	(27)	
(00)	STEEDING ASSEMBLY (SPECIFIC AREA LINICAGAN)	(44)	
(09)	,	(85)	
(65)		(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)		(91)	
(59)	TRANSMISSION LEVER ON COLUMN		
		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	, ,	
(84)	PARKING BRAKE HANDLE IN FRONT	(26)	
	IGNITION KEY	(24)	
(67)		(18)	DOME LIGHT
(06)	MIRROR	(39)	BACKLIGHT HEADER
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	ROOF MOUNTED CONTROLS/CONSOLE
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	
(08)	RADIO (BUILT IN)	(/	
(58)	ADD-ON TAPE DECK, RADIO, A/C	FYTERIC	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES		OUTSIDE SURFACE OF CASE VEHICLE
(,		(37)	
REAR			(SPECIFIC AREA UNKNOWN)
	OUDELOS OS OS OS AS ASTRONOS	(35)	HOOD OF CASE VEHICLE
	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
	REAR WINDOW		OUTSIDE MIRRORS, ANTENNA, TRIM)
(39)	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
INTERIO	R-GENERAL	(5.)	THE OF ONCE VEHICLE
(11)	TRANSMISSION SELECTION LEVER (LOCATION UNK.)	BEYOND	CASE VEHICLE BOUNDARY
(59)			
(44)			AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(70)	HOOD OF OTHER VEHICLE
(84)		(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
	PARKING BRAKE HANDLE IN FRONT		OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
		(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
	ARMREST ON SEAT		
(89)		(79)	WATER
(00)	ONDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(20)	DECTRAINT CVCTEM HARDWARD		OR WATER. PLEASE DESCRIBE.)
	RESTRAINT SYSTEM HARDWARE	_	_
	RESTRAINT SYSTEM WEBBING	PENETRA	ATING OBJECTS
	AIR CUSHION SKIN (AIRBAG)	(61)	OTHER VEHICLE
	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS	, - <b>,</b>	· (,
(48)	KNEE RESTRAINT	MISCELLA	ANFOLIS
(30)	HEAD RESTRAINT		
	CHILD SEAT RESTRAINTS	(00)	NO CONTACT (INVALID FIELD FORM CODE)
	CHILD SEAT		OTHER (E.G. FIRE. DESCRIBE)
	INTERIOR LOOSE OBJECT	, ,	SPARE TIRE
(31)		• • •	INDUCED
(20)		(6.50)	
	OTHER OCCUPANT(S)	(97)	EJECTED, UNKNOWN CONTACT
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	11	EJECTED, UNKNOWN CONTACT IMPACT FORCE, "WHIPLASH",
(52)		11	
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	IMPACT FORCE, "WHIPLASH",



## CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

## 1 BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

## 3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

## 4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (i) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

# 2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

# SEVERITY 5 SYSTEM/ORGAN 4 LESION 5 ASPECT 0 BODY REGION 1

#### 5 SEVERITY (OR \*AIS\*, ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN



















t Availab



























Best Availab







Available

























CASE NO. 200-20 CASE VEHICLE 1998 Fors TYPE F-195. 6x2 2-deer places OCCUPANT planner bluese eld male SWALING 190 DEPER 3 MY MADE 7943 (1990) SWALINGTON 3 point bett som anlang deployed



## PN 22900 #38